W-03880A-06-02G8 W20459A06 0298

## Arizona Department of Environmental Que ORIGINA Drinking Water Monitoring and Protection 1110 W. Washington Street, 5415B-1



2

57

## **Drinking Water Compliance Status Report**

Phoenix, AZ 85007

Public Water System Name:	Gardner WC						
Public Water System ID #:	04-038						
Public Water System Type:	[] Community [] Non-transient Non-community [X] Transient Non-community					¥.	
Overall Compliance Status:	[X] No Major Deficien	cies [] Major Defic					
Monitoring and Reporting Status: Comments:	[X] No Major Deficien	cies [] Major Defic	[] Major Deficiencies		Arizona Corporation Commission DOCKETED		
					13 20		
<b>Operation and Maintenance Status:</b> Comments:	[X] No Major Deficien	cies [] Major Defic	ciencies	DOCKETE	D BY		
Major unresolved/ongoing operation and maintenance deficienc  [] unable to maintain 20psi [] cross connection/backflow problems [] treatment deficiencies [] certified operator  Date of last inspection / sanitary survey:6-11-04  Administrative Orders:  Is an ADEQ administrative order in effect? [] Yes  Comments:		ies:  [] inadequate storage  [] surface water treatm  [] approval of construct  [] other  [X] No		2001 MAR 13 12 3:	RECEIVED		
System information:			rž	<u>ω</u>			
Number of Entry Points to the Distribution System 2		Number of Sources	2				
oulation Served 160 Service Connections 84		Initial Monitoring Year 1995					
Evaluation completed by: Jim P	uckett						
Phone: 602-771-4649 Date:	3-12-07						

Based upon data submitted by the water system, ADEQ has determined that this system is currently delivering water that meets water quality standards required by Arizona Administrative Code, Title 18, Chapter 4. This compliance status report does not guarantee the water quality for this system in the future. This compliance status report does not reflect the status of any other water system owned by this utility company.